
8" Minimum clearance from Top of window bracket to the ceiling
Window Bracket may be mounted lower on the window frame if clearance is not sufficient
Transom Window Hinged at Bottom
12" Minimum
Adjust as needed
Pull Down to Operate
12" Minimum from Bottom of of operator to the Bottom on Guide


Transom Window Hinged at Top
12" Minimum
Adjust as needed
12" Minimum from Bottom of of operator to the Bottom on Guide
Push Up to Operate