


CRYSTORAMA LIGHTING

Crystorama.com


ASSEMBLY INSTRUCTION MODEL #8826-GA-CL-MWP







All electrical components must be installed by a licensed electrician in accordance with the National Electric Code and the appropriate local electrical codes.



You will need 6-Candelabra Base Bulb

40Watts Recommended 60 Watts Max.

USE LED BULBS FOR EXTENDED USE

How to Install

1.Do a complete inventory of all parts and components before you start installing
2.Place the crystal bobeche and metal washer over the cap on the top of fixture and secure them with fixture loop.
3.After safely attaching fixture into outlet box, install the bulbs and proceed with connecting the power.
4.When you begin to dress the fixture, start with packet labeled (A)
5.IMPORTANT: Apply crystal sets in alphabetical order

Crystal Sets

A. (14mm+50mm)x42sets

B. (10mm Ball x26)x1set


C. 40mm Ballx1set

WARNING: This product can expose you to Lead, which is known to the State of California to cause cancer and/or birth defects or reproductive harm. For more information go to www.P65Warnings.ca.gov

CRYSTORAMA LIGHTING

Crystorama.com

ASSEMBLY INSTRUCTION MODEL #8826-GA-CL-MWP



Part Number

Part Numbers

A. (3)-Wire Connector
B. (1)-Mounting Plate
C. (1)-Ground Screw
D. (1)-Nipple
E. (2)-Outlet Box Screws
F. (1)-Canopy (W5.1″xH1″)XEH8828GACAN5IN
G. (1)-Collar Loop
H. (1)-Collar Ring
I. (1)-Chain;72″,4mm XEH8828GACHA4MM
J. (1)-Loop
K. (1)-Metal Washer
L. (1)-Bobeche (D3.9″x Hole:1″) XEH6623BOB4IN
M. (1)-Frame
N. (6)-Metal Sleeve (H4.2”) XEH8826GAMCDL4.2IN
O. (6)-Plastic Sleeve (H4.2”) XEH8826GAPCDL4.2IN